

KEEWAY FACT 50X '26-

Windshield Traffic Model Windshield Urban Model

REF. 23152
REF. 23153




ID.	PIEZA/PART	DESCRIPCIÓN	DESCRIPTION	QTY.	REF.:
1		Cúpula Trafic	Windshield Traffic	1	10593
		Cúpula Urban	Windshield Urban	1	10940
2		Tapa exterior	Exterior cover	2	CONJU-S3PCC-003
3		Soporte rótula exterior	Ball bearing exterior support	2	BRIROT02-1-PR16
4		Soporte rótula interior	Ball bearing interior support	2	BRIROT01-1-PR16
5		Tornillo allen M5x20 DIN912	M5x20 DIN912 allen screw	4	TORNI-AD912-464
6		Tuerca autoblocante M5 DIN982	M5 DIN982 lock nut	4	TUERCA-D982-746
7		Tornillo phillips M5x13	M5x13 phillips screw	4	TORNIP510---233
8		Varilla Ø9x140mm 90°	Rod Ø9x140mm 90°	2	CJROTEXC-0-P140
9		Tapón final varilla	Final bar cap	2	TOPEE-VPGT--8/4
10		Tornillo M8x40 DIN912	M8x40 DIN912 screw	2	TORNI-AD912-475
11		Soporte guía sujección varilla	Rod guide support	2	FIXVARLL-0-PR16
12		Acoplamiento esquadra	Coupling angle	2	FIXSOPOR-0-PR16
13		Esquadra	Angle	2	SOPORT30X30-581
14		Caperuza plana M8	M8 nut cover	2	CAPERUZTOM8-047
15		Tuerca M8 DIN6923	M8 DIN6983 nut	2	TUERCEG6923-249
16		Tapón tornillo M8 DIN912	M8 DIN912 screw cap	2	TAPA--CHC11450E
17		Embellecador faro	Headlight trim	1	EMBELLECEDOR-01

KEEWAY FACT 50X '26-


Windshield Traffic Model Windshield Urban Model

REF. 23152
REF. 23153

MOD. TRAFIC



MOD. URBAN



PREVENCIÓN:

- Usar agua y jabón neutro para limpiar la pantalla.
 - Revisar periódicamente el apriete de la tornillería.
 - Estacionar el scooter en dirección al sol, evitando el efecto lupa que puede dañar algunas partes.
 - Aparcar, si es posible, en superficies niveladas.
- Gracias por su atención.

PREVENTION:

- Use water and neutral soap to clean the windshield.
- Check the tightening of the fasteners periodically.
- Park the scooter facing the sun, avoiding the sun-reflection effect that may damage some parts.
- Park if possible on even surfaces.

Thanks for your attention.

